

	Matrix Verwendung Spiraldorne					Abmessung Dorn		4,35 x 0,80	4,45 x 0,85	4,70 x 1,60	4,80 x 1,50	4,90 x 1,20	4,90 x 1,43	5,00 x 1,20	5,10 x 0,70	5,10 x 0,90	5,10 x 1,20	5,50 x 0,90	6,00 x 1,00	6,00 x 1,80	6,10 x 1,40	6,40 x 0,90	6,50 x 0,90	6,60 x 1,70	6,70 x 0,90	7,25 x 1,90	7,60 x 1,05	8,00 x 1,00		8,35 x 2,00	8,40 x 1,40	8,50 x 1,00	11,40 x 3,30	13,50 x 4,60			
	Stand 03.12.2015					Stückzahl Dorne		8	8	8	1	12	9	13		6	10	4		12	10	2	11	2	1	7	8	1		4			2	2			
				Bisher eingesetzt auf			Flachwickler 3.200																														
							Rundwickler 5.000																														
							Rundwickler 7.500																														
Spiraldraht- abmessung	Siebtype		Spiraldraht	Standard	Spezial	Spiralmaß						?				?							?				?			?	?	?					
	0,90	90000 S		190 H	x		9,80 x 4,40																							x							
	0,90	90300 S		190 H	x		9,80 x 4,40																							x							
	0,90	90400 S		190 H	x		9,80 x 4,40																							x							
	0,90	90500 S		190 H	x		9,80 x 4,40																							x							
	1,00	100000 S9		190 H	x		9,90 x 4,85																							x							
	1,00	100000 S10		190 H	x		9,00 x 4,65																														
	1,00	100000 S12		190 H	x		9,80 x 4,85																								x						
	1,00	100500 S9		190 H	x		9,90 x 4,85																								x						
	1,20	120000 S		190 H	x		14,80 x 8,00																											x			
	2,00	200000 S		190 H	x		16,70 x 10,50																											x			
	0,43 x 0,70	43000 FH		190 HS		x	5,20 x 2,90							x																							
	0,43 x 0,70	43000 FHL		190 HS		x	6,75 x 2,90																	x													
	0,43 x 0,70	43090 FHL		190 HS		x	6,75 x 2,90																	x													
	0,43 x 0,70	43110 FHL		190 HS		x	6,75 x 2,90																	x													
	0,43 x 0,70	43125 FHL		190 HS		x	6,75 x 2,90																	x													
	0,43 x 0,70	43150 FHL		190 HS		x	6,75 x 2,90																	x													
	0,43 x 0,70	43200 FHL		190 HS		x	6,75 x 2,90																	x													
	0,43 x 0,70	43250 FHL		190 HS		x	6,75 x 2,90																	x													
	0,43 x 0,70	43300 FHL		190 HS		x	6,75 x 2,90																	x													
	0,43 x 0,70	43400 FHL		190 HS		x	6,75 x 2,90																	x													
	0,43 x 0,70	43500 FHL		190 HS		x	6,75 x 2,90																	x													
	1,00	100000 H9-CE		190 HS		x	9,00 x 4,60																	x													
	0,43 x 0,70	43000 FT		190 HF2		x	5,20 x 2,90							x																							
	0,43 x 0,70	43000 FTL		190 HF2		x	6,75 x 2,90																	x													
	0,43 x 0,70	43090 FTL		190 HF2		x	6,75 x 2,90																	x													
	0,43 x 0,70	43110 FTL		190 HF2		x	6,75 x 2,90																	x													
	0,43 x 0,70	43125 FTL		190 HF2		x	6,75 x 2,90																	x													
	0,43 x 0,70	43150 FTL		190 HF2		x	6,75 x 2,90																	x													
	0,43 x 0,70	43200 FTL		190 HF2		x	6,75 x 2,90																	x													
	0,43 x 0,70	43250 FTL		190 HF2		x	6,75 x 2,90																	x													
	0,43 x 0,70	43300 FTL		190 HF2		x	6,75 x 2,90																	x													
	0,43 x 0,70	43400 FTL		190 HF2		x	6,75 x 2,90																	x													
	0,43 x 0,70	43500 FTL		190 HF2		x	6,75 x 2,90																	x													
	0,55	55000 T		190 H		x	5,10 x 3,20					x																									
	0,55	55000 TL		190 H		x	6,70 x 2,80																			x											
	0,55	55200 TL		190 H		x	6,70 x 2,80																		x												
	0,60	60000 T		T		x	5,40 x 3,20				x																										
	0,70	70000 T		190 HF2		x	6,80 x 3,80													x																	
	0,70	70000 T+		930 CK		x	6,80 x 3,80													x																	
	0,70	70000 T7		190 HF2		x	6,80 x 3,80													x																	
	0,70	70000 T7+		930 CK		x	6,80 x 3,80													x																	

	Matrix Verwendung Spiraldorne					Abmessung Dorn		4,35 x 0,80	4,45 x 0,85	4,70 x 1,60	4,80 x 1,50	4,90 x 1,20	4,90 x 1,43	5,00 x 1,20	5,10 x 0,70	5,10 x 0,90	5,10 x 1,20	5,50 x 0,90	6,00 x 1,00	6,00 x 1,80	6,10 x 1,40	6,40 x 0,90	6,50 x 0,90	6,60 x 1,70	6,70 x 0,90	7,25 x 1,90	7,60 x 1,05	8,00 x 1,00		8,35 x 2,00	8,40 x 1,40	8,50 x 1,00	11,40 x 3,30	13,50 x 4,60			
	Stand 03.12.2015					Stückzahl Dorne		8	8	8	1	12	9	13		6	10	4		12	10	2	11	2	1	7	8	1		4			2	2			
				Bisher eingesetzt auf			Flachwickler 3.200																														
							Rundwickler 5.000																														
							Rundwickler 7.500																														
Spiraldraht- abmessung	Siebtype		Spiraldraht	Standard	Spezial	Spiralmaß						?				?							?				?			?	?	?					
	0,70	70300 TL		190 HF2		x	8,40 x 3,40																				x										
	0,70	70400 TL		190 HF2		x	8,40 x 3,40																				x										
	0,70	70600 TL		190 HF2		x	8,40 x 3,40																				x										
	0,75	75000 TC7		T		x	6,90 x 3,60																x														
	0,90	90000 T		HF 2		x	9,80 x 4,40																								x						
	1,05	105000 T9		HF 4		x	10,10 x 4,70																								x						
		60000 SL M-10				x																															
	0,70	70000 A		814 L		x	6,80 x 3,80													x																	
	0,70	70000 S7 A-5		814 L		x	6,80 x 3,80													x																	
	0,70	70000 S7 A-10		814 L		x	6,80 x 3,80													x																	
		70000 A7L				x																						x									
	0,70	70000 S7L A-5		814 L		x	8,40 x 3,40																					x									
	0,70	70000 S7L A-10		814 L		x	8,40 x 3,40																					x									
	0,70	70250 S7L A-5		814 L		x	8,40 x 3,40																					x									
	0,70	70250 S7L A-10		814 L		x	8,40 x 3,40																					x									
	0,70	70400 S7L A-5		814 L		x	8,40 x 3,40																					x									
	0,70	70400 S7L A-10		814 L		x	8,40 x 3,40																					x									
	0,70	70600 S7L A-5		814 L		x	8,40 x 3,40																					x									
	0,70	70600 S7L A-10		814 L		x	8,40 x 3,40																					x									
	0,70	70000 S7L M-4		814 L		x	8,40 x 3,40																					x									
	0,70	70000 S7L M-8		814 L		x	8,40 x 3,40																					x									
	0,60	60000 L		190L		x	5,40 x 3,20				x																										
	0,60	60000 L9		190L		x	5,40 x 3,20				x																										
	0,60	60000 L9L		190L		x	6,80 x 3,25															x															
	0,60	60000 LL		190L		x	6,80 x 3,25															x															
	0,70	70000 L		190 L		x	6,80 x 3,80													x																	
	0,70	70000 L7		190 L		x	6,80 x 3,80													x																	
	1,00	100000 L9		190 L		x	9,80 x 4,85																									x					
	1,00	100000 L9-CE		190 L		x	9,00 x 4,60																									x					
	1,00	100000 L12		190 L		x	9,80 x 4,85																									x					
	0,60	60000 LPPS		M709.19		x	5,40 x 3,20									x																					
	0,60	60000 LPPS9		M709.19		x	5,40 x 3,20									x																					
	0,60	60000 LPPSL		M709.19		x	6,80 x 3,40																	x													
	0,60	60000 LPPSL9		M709.19		x	6,80 x 3,40																	x													
	0,60	60000 PPS		75 E		x	5,40 x 3,20								x																						
	0,60	60000 PPS9		75 E		x	5,40 x 3,20								x																						
	0,60	60000 PPSL		75 E		x	6,80 x 3,40																	x													
	0,60	60000 PPSL9		75 E		x	6,80 x 3,40																	x													
	0,60	60300 PPSL		75 E		x	6,80 x 3,40																	x													
	0,60	60400 PPSL		75 E		x	6,80 x 3,40																	x													
	0,60	60500 PPSL		75 E		x	6,80 x 3,40																	x													

[illegible]